

1931

OAKLAND SERVICE SHOP MANUAL

1931 Supplement

To Section One

FRONT AXLE

This Supplement contains full Information and Specifications for the 1931 Oakland Eight and Pontiac Six not included in the 1930 Edition of the "Oakland Service Shop Manual." Specifications not listed herein are the same as for 1930 and will be found in the 1930 Section of the "Oakland Service Shop Manual."

Insert this supplement in the "Oakland Service Shop Manual" following Section I

1931




Illustration 31-1-2. Steering Third Arm 1931 Pontiac Six